




<p>A x 14</p>  <p>$\phi 6 \times 35\text{mm}$</p>	<p>B x 14</p>  <p>$\phi 15 \times 12\text{mm}$</p>	<p>C x 16</p>  <p>$\phi 8 \times 30\text{mm}$</p>	<p>D x 28</p>  <p>$3.5 \times 14\text{mm}$</p>
<p>E x 4</p> 	<p>F x 2</p> 	<p>G x 16</p>  <p>$4 \times 35\text{mm}$</p>	<p>H x 16</p>  <p>$M6 \times 12\text{mm}$</p>
<p>I x 10</p>  <p>$\phi 7 \times 40\text{mm}$</p>	<p>J x 2</p> 	<p>K x 2</p>  <p>$M4 \times 18\text{mm}$</p>	<p>L x 1</p>  <p>M4</p>
<p>M x 4</p> 			




1



A	x 10
$\phi 6 \times 35\text{mm}$	

2




A	x 4
	
$\phi 6 \times 35\text{mm}$	

D	x 4
	
$3.5 \times 14\text{mm}$	


F	x 2
	

3



B	x 4
	
$\phi 15 \times 12\text{mm}$	


4




B	x 6
	
ø15 x 12mm	

C	x 4
	
ø8 x 30mm	


5




B	x 4
	
ø15 x 12mm	

C	x 4
	
ø8 x 30mm	

6



7




C	x 8
	
$\phi 8 \times 30\text{mm}$	

I	x 10
	
$\phi 7 \times 40\text{mm}$	

L	x 1
	
M4	


8



x4

G	x 16
	
4 x 35mm	


9



H	x 16
	
M6 x 12mm	

L	x 1
	
M4	

10




D	x 8
	
3.5 x 14mm	

J	x 2
	

K	x 2
	
M4 x 18mm	



M	x 4
	

11



D	x 16
	
3.5 x 14mm	

12



13

