




A	x 20	B	x 20	C	x 12	D	x 17
							
$\phi 6 \times 35\text{mm}$		$\phi 15 \times 12\text{mm}$		$\phi 8 \times 30\text{mm}$		$3.5 \times 14\text{mm}$	
E	x 8	F	x 4	G	x 25	H	x 16
							
$\phi 7 \times 40\text{mm}$				$4 \times 35\text{mm}$		$M6 \times 12\text{mm}$	
J	x 2	K	x 2	L	x 1	M	x 1
							
		$M4 \times 18\text{mm}$		$M4$		$\phi 6 \times 30\text{mm}$	
N	x 1						
							




1




A	x 8
$\phi 6 \times 35\text{mm}$	

2



F	x 4

3




A	x 4
$\phi 6 \times 35\text{mm}$	

D	x 8
$3.5 \times 14\text{mm}$	


F	x 4

4



B	x 4
	
$\phi 15 \times 12\text{mm}$	


5



B	x 6
	
$\phi 15 \times 12\text{mm}$	

C	x 4
	
$\phi 8 \times 30\text{mm}$	


6



B	x 2
	
ø15 x 12mm	

C	x 2
	
ø8 x 30mm	

7




C	x 6
	
ø8 x 30mm	

E	x 8
	
ø7 x 40mm	

L	x 1
	
M4	


8



x4

G	x 16
4 x 35mm	



9



H	x 16
M6 x 12mm	

L	x 1
M4	

10






G	x 1
4 x 35mm	

M	x 1
ø6 x 30mm	


N	x 1

11



D	x 1
3.5 x 14mm	


12



x2

A	x 8
φ6 x 35mm	


13



x2


G	x 8
4 x 35mm	

14



x2

15




x2

B	x 8
	
Ø15 x 12mm	

J	x 2
	

K	x 2
	
M4 x 18mm	

16



D	x 8
	
3.5 x 14mm	

F	x 4
	

17

