











Assemble Instruction

<p>A</p>  <p>x1</p> <p>B</p>  <p>x1</p>	<p>1.</p>  <p>M6*20</p> <p>M6*20</p> <p>M6-20 X4</p>	<p>2.</p>  <p>M8-25 x2</p> <p>⊗ x2</p>
<p>C</p>  <p>x1</p> <p>D</p>  <p>x1</p> <p>E</p>  <p>x2</p>	<p>3.</p>  <p>M8-70 x2</p>	<p>4.</p>  <p>M6-25 x4</p>
<p>M6-20 X4</p> <p>M8-25 x2 ⊗ x2</p> <p>M8-70 x2</p> <p>M6-25 x4</p> <p>M6x1</p> <p>M8x1</p> <p>x1</p> 	<p>5.</p> 